Is it time for an update?

Presenter: Capt. Peter Dann Adapted from original presentation by Craig Eastaugh

Is it time for an update?

WHY?

- Every ship has its own pilot card version there is no standard version
- Pilot cards are not written for pilots
- Pilot cards don't provide timely information
- Modern pilotage requires much more detailed information
- We now have the ability to use technology to improve the information transfer

Is it time for an update?

What should the format be?

- Suitable for paper and electronic devices
- App based?
- Universal file format PDF?
- Selectable information tabs
- Click and drag items where suitable
- Easily upload information to (pilot card) page

Is it time for an update?

Page to input ship type

Is your vessel a:

- Bulk carrier
- Geared bulk carrier

Where are the cranes located

What is the obscured arc

• Tanker

Bridge to manifold distance – inserts manifold schematic

• Containership


Bridge to bow distance - modifies the bridge position on the diagram

• Cruise ship

Bridge to bow distance – forward bridge


Modifies the machinery page for Azi-pods etc






Is it time for an update?

Manoeuvring Information



Is it time for an update?

Manoeuvring Information



Is it time for an update?

Ships Particulars

SHIP'S PARTICULARS

M.V. BLUE RIDGE HIGHWAY		
VEHICLES CARRIER		
PANAMA / PANAMA		
41123-10-В		
3FEY4		
9510151		
355558000		
6005519 / 036377		
Nantong COSCO KHI Ship Engineering Co., Ltd.		
22N1603 (NE055)		
15 December 2008		
25 August 2009		
18 December 2009		
16th~29th Nov. 2017/Zhoushan, CN (ZESCO – Zhejiang Eastern Shipyard Co., Ltd.)		
NIPPON KAUI KYOKAI (NK) / 092424		
UK P & I CLUB		
179.990 M (590.52 Ft.) / 167.000 M (547.90 Ft.)		
32.200 M (105.64 Ft.)		
9,400 M (30,832 Ft.)		
15,290 MT / 28,854 MT		
Gross: 48,927 Net : 14,679		
Gross : 29,962		
Gross: 160,892 Net: 48,896		
Gross : 54,132.36 Net : 50,458.20		
Gloss . 34,132.30 Net : 50,458.20		
14.980 M (49.15 Ft.)		
32.210 M (105.68 Ft.)		
45.700 M (149.896 Ft.)		
KAWASAKI MAN B&W 7S60ME-C x1SET		
17,010 PS (12,500 kW) x 99 rpm		
14,460 PS (10,630 kW) x 94 rpm		
20.0 KTS (Speed on the designed draft of 8.40M at normal output with 15% sea margin)		
47.1 MT/DAY (44.6 MT/Day for M/E; 2.5 MT/Day for G.F.)		
1,200 HP (920 kW) x 1200 rpm		
ETERNITY MARITIME SHIPPING S.A.		
5452513		
53 ^{al} Street, Urbanizacion Obarrio Torre Swiss Bank, 16 th Floor		
Panama, Republic of Panama		
FUKUNAGA KAIUN CO., LTD. 0208570		
5-8, Tokiwahigashi-machi, Saiki-shi, Oita-ken, 876-0851, Japan Tel.: +81 972 22 5116; Fax: +81 972 22 5949 eMail: flincipn@fline.co.jp		
(K') INE (KAN/ACAKI KIOPALIA AMARANA		
"K"LINE (KAWASAKI KISEN KAISHA, LTD. lino Building 1-1 Uchisaiwaicho 2-Chome, Chiyoda-ku, Tokyo 100-8540, Japan		
870 764949034 / 764949035 / 764949036		
870 764949034 7 764949035 7 764949036 870 783242569		
870 783242569 870 773206809		
435555810		
435555810 postmaster.3FEY4@globeemail.com		
435555810		

Is it time for an update?

Machinery

Main Engine	Propeller	Rudder	Thruster
Number:	Number:	Number:	Bow
Туре:	Type: CPP / Fixed	Type:	Number:
Fuel:	Left / Right hand	Max angle:	Power (kW):
MCR:	turning	Time hard over to	Control: Step/Variable
NCR:		hard over:	
No of Starts:			Stern
Load program in			Number:
manoeuvring range? Y/N			Power (kW):
			Control: Step/Variable

Is it time for an update?

Manoeuvring Speed Table


AH	EAD	ASTERN
	AHEAD	
P.M.	SHIP SPEED (KNOTS)	(R.P.M.)
55	11.9	55
18	10.4	48
12	9.1	42
27	5.8	27
	P.M. 55 18 12 27 30 ~ 38	(KNOTS) 55 11.9 48 10.4 42 9.1 27 5.8

Is it time for an update?

Towage Fittings and Mooring Machinery

Have a ship shape with click and drag winches, bitts & fairleads.


Have SWL on each item



Panama Lead



Bitts - Towing



Roller Lead



The Pilot Card

Is it time for an update?


Towage Fittings and Mooring Machinery




Is it time for an update?

Visibility Diagram


(both horizontal and vertical – include cranes)





Is it time for an update?

Windage Diagram / Calculations




Is it time for an update?

Portable Pilotage Unit Page

Does the conning position have room for a PPU? Does the conning position have an AIS plug? Does the conning position have a power plug? What are the AIS offsets? Is the AIS information up to date?


Are the bridge wings suitable for magnetic antennas?


Does the bridge wing have a suitable place for a PPU (Laptop/iPad) to be placed during berthing?



Is it time for an update?

RO-RO Ramp Diagram / Pax Vessel Access door Diagram





Is it time for an update?

General Vessel Information

(not covered elsewhere)

- Unusual cargo on deck– overhanging, reduced visibility etc
- Unusual vessel handling characteristics
- Fuel issues any change over problems
- Main engine is slow to fire (Time?)

Is it time for an update?

Photos


- Vessel general
- From the conning position forward
- Bridge wing layout
- Helicopter deck
- Unusual cargo on deck (overhangs etc)

Is it time for an update?

View from the Conning Position







Is it time for an update? View of the Bridge Wing



Is it time for an update?

Helicopter deck layout





Is it time for an update?

What Next?

- Is this the right way to go?
- Agree on final format
- Work out best platform for presentation and file transfer
- Trial run in a port with selected ships
- National (AMPI) agreement
- IMPA
- ICS
- ???